

Type	mm	Diagram 1		Diagram 2		Intermittent	Intermittent	45°	O-RING	Special	Non-ferrous metals	Tough, difficult to break	Soft, "sticky", built-up edge	Heat-resistant, aust. stainless	Chip breaking	Type of swarf	Catalogue page	Application
		mm	mm	mm	mm													
MT	2-12	○	○	●	●	○	○		●	○	○	○	○	○	○	○	A130	MT MTr
MTr				$D_{1\min}=20$	$D=20-\infty^1)$													
MTb	3-12	○	○	●	○	○	○			○	○	○			●		A131	MTb
MTc	3-12	○	○	●	●	○	●			○	○	○	○	○	○		A132	MTc
MS	2-12	●	●	●	○	●	○				○			○	○	●	A132	MS
R/LMS	2-10	○	●			●					○			○	○	●	A133	R/LMS
MZ	2-12	●	●	●	●	○	○				○	●	○	●	●	○	A134	MZ
R/LMZ	3-4	○	●			○					○	●	○	●	●	○	A134	R/LMZ
MP	2-8	○	○	●	●	○	●				●	○	●	●	○	●	A135	MP
MA	2-5	●	●	●	●	○	●			○	●	○	●	●	○	●	A136	MA
R/LMA	2-4	○	●			○					●	○	●	●	○	●	A136	R/LMA
MB	3-5	○	○	●	●	○	●				●	○	●	●	○	○	A137	MB
B	2-8	●						●			○	○	○	○			A138	B
G	0,5-3,15			●							○	○	○	○			A138	G
E	2-5			●	●		○				○	○	○	○	●		A139	E
H	0,4-2,0			●							○	○	○	○	●		A140	H
K	4-10		○	●			○				○			●			A145	K
R/LK	6, 8		●											●			A145	R/LK

● Recommended  
Empfohlen  
Rekommenderat

○ Alternative  
Alternativ

○ Recommended to limited extent  
Empfohlen in begrænset omfang  
Rekommenderas i begränsad omfattning

<sup>1)</sup> D=20-35 mm  
Type «X» ou «Z»  
Typ «X» con «Z»  
Typ «X» o «Z»

<sup>2)</sup> D=20-50 mm  
Type «XU», «ZU» ou «U»  
Typ «XU», «ZU» con «U»  
Typ «XU», «ZU» o «U»

